









d_0	$\varnothing 8\text{mm}$







A8 $h_{nom}=70\text{mm} \mid t_{fix2}=0...10\text{mm}$

HUS3-C 8	t_{fix1}	$t_{fix1}+t_{fix2}$
8x75	5 mm	5...15 mm
8x85	15 mm	15...25 mm






d_0	$\varnothing 8\text{mm}$	$\varnothing 8\text{mm}$	$\varnothing 6\text{mm}$



B5

	h_{nom1}	h_{nom2}	h_{nom3}
HUS3-C 8	=50mm	=60mm	=70mm
	t_{fix1}	t_{fix2}	t_{fix3}
8x65	15 mm	-	-
8x75	25 mm	15 mm	-
8x85	35 mm	25 mm	15 mm



		d_0
d_0	$\varnothing 8\text{mm}$	

